

ULPOWER AERO ENGINES N.V

Zonnebeekseweg 379
B-8900 Ieper
Belgium

SERVICE BULLETIN

Tel. +32 57 46 61 20
Fax +32 57 44 52 21
e-mail: info@ulpower.com

Service Bulletin No. 2016-

01BIS

SUBJECT: Fuel lines from fuel connection kit K020001 / K020007 / K020008

MODELS AFFECTED: All models

TIME OF COMPLIANCE: before next flight

AFFECTED SERIAL NUMBER: all engines with serial number lower than 140101

Problem: fuel leaks on the pressure line indicated by some customers.

Solution: We found that the effected fuel lines were all older then 2014.
From 01/01/ 2014 we changed to Aeroquip-hoses which have proven quality.

Action:

Check if engine serial number is lower than 140101.

If yes, replace fuel lines by new lines with article number F2550002 (AQP-hose)
(36 EUR/ m)



SB 2016-							
Issued			Revised			Page	Revision
Mo	Day	Year	Mo	Day	Year	1 of 1	0
03	09	2016					