



**AEROPILOT Ltd.**

**LEGEND**

RELEASE DATE: 31.08.2023    EFFECTIVE DATE: 31.08.2023    NOTICE ID: 2307

## SERVICE BULLETIN

**SUBJECT:**

Stabilizer pin

**AFFECTED PRODUCT:**

Legend 540 and Legend 600

**COMPLIANCE:**

Mandatory

**INSTRUCTIONS:**

Due to the possibility of fatigue damage of the stabilizer connection pin, it is necessary to check these pins in Legend 540 and Legend 600 aircrafts. The connection diagram of the stabilizer pin is in the attachment.

Ing.  
Jaromír  
Smékal

Digitálně  
podepsal Ing.  
Jaromír Smékal  
Datum:  
2023.08.31  
08:31:23 +02'00'

---

AEROPILOT Ltd.  
1815 Jeníkovská  
28601 Čáslav  
Czech Republic

Tel.: +420 605 296 563  
E-mail: [info@aeropilotcz.com](mailto:info@aeropilotcz.com)  
[www.aeropilotcz.com](http://www.aeropilotcz.com)  
VAT: CZ27108431

