



**AEROPILOT Ltd.**

**LEGEND**

**RELEASE DATE: 31.08.2023**

**EFFECTIVE DATE: 31.08.2023**

**NOTICE ID: 2307**

## **SERVICE BULLETIN NO. 2307**

### **SUBJECT:**

Stabilizer pin

### **AFFECTED PRODUCT:**

Legend 600 aircraft serial numbers: 1854, 1971, 2073, 2081, 2183, 2184, 2185, 2189, 2190, 2191, 2192, 2193, 22100, 22107

### **COMPLIANCE:**

Mandatory

### **INSTRUCTIONS:**

Due to the possibility of fatigue damage of the stabilizer connection pin, it is necessary to check these pins in the Legend 600 aircrafts. The connection diagram of the stabilizer pin is in the attachment.